

**County:** Adams

**Township:** 1S      **Range:** 68W      **Section:** 10      **QQ:** SESE

**Original Latitude/ Longitude:** 39.973918 / -104.980695

**Updated Latitude/ Longitude:** /

**Basis for Location Change:**

<b>Field Inspection Date:</b>	<b>Document #:</b>
<b>Pit Still Present in Field:</b> No	
<b>Visible Surface Impacts:</b> <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
<b>Inspection Notes:</b>	
<b>Operator Required to Submit Form:</b> NA	<b>Due Date:</b>
<b>Form Request Sent To:</b>	<b>Sent Date:</b>

## Pit Status Evaluation:

### Pit Status Review Documents:

- |                                     |   |                  |
|-------------------------------------|---|------------------|
| <input type="checkbox"/>            | Form 15 Pit Permit – Doc #: NA                  | Date: NA         |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 664646             | Date: 10/18/1988 |
|                                     | Doc #: 316227                                   | Date: 1/20/1997  |
|                                     | Doc #:  | Date:            |
| <input checked="" type="checkbox"/> | Form 27 Remediation Workplan – Project #: 11446 | Date: 6/14/2018  |
| <input type="checkbox"/>            | Form 4 Sundry Notice – Doc #:                   | Date:            |
| <input type="checkbox"/>            | COGIS Document – Doc #:                         | Date:            |
| <input type="checkbox"/>            | Pit Inventory – Doc #:                          | Date:            |
| <input type="checkbox"/>            | Duplicate Record – Duplicate Pit(s) #:          |                  |
| <input checked="" type="checkbox"/> | Aerial Photo Verification (photos attached)     |                  |
| <input type="checkbox"/>            | Other:  |                  |

### Pit Status Determination

**Updated Pit Status: Closed**

**Pit Status Date: 7/10/2018**

#### Timing of Pit Closure:

Vault removed under remediation project #11446, closed 7/10/2018

#### Pit Status Review Summary:

Based on records review and aerial photos, there is no evidence that there was a produced water pit on location. Inspection reports document a concrete water vault on location. The vault was removed under remediation project #11446 (closed 7/10/2018). Pit status has been changed to closed.

