

Davis #2-5

Corrective Actions Taken on the Davis #2-5 for the COGCC compliance
INC.

Davis #2-5 07/03/19



Storm Water management controls have been established to stabilize erosion along center and west side of access road. Check dams and diversions were installed to control water run off from location.



View pad looking north, northwest of access road.



View of check dam and diversions looking north, northwest.



View of check dam and diversions looking north, northwest.



View of location entrance looking south, southwest.

The green plastic debris (Synthetic erosion netting) identified on the cut slope has been removed and properly disposed of. Cut slope diversions have been cleaned and disturbed areas seeded. Wattles were installed to stabilize the cut slope from eroding while vegetation re-establishes.



View of project area looking North.

