

Inspection Photos

Loc#324754

Operator: Sandridge

Inspection Number: 692401152

Inspection Date: 6/27/19





Photo#1:
Overview of Location from Entry to Southwest.

June 27, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Spicer Loc#324754



Photo#2:
Pooling oil and staining in tank containment.



Photo#3:
Pooling oil and staining in tank containment

June 27, 2019



Photo#4:
Pooling oil and staining in tank containment



Photo#5:
Pooling oil and staining in tank containment

June 27, 2019



Photo#6:
Views of Interim Reclamation area.

June 27, 2019



Photo#7:
Berm area of concern in NW portion of Interim.
Insert is close up of berm material.



Photo#8:
Area of concern in South portion of Interim. Insert is
close up of chip material and ground conditions.

June 27, 2019



Photo#9:
Lack of BMPs along access road.



Photo#10:
Lack of BMPs along access road.

June 27, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Spicer Loc#324754



Photo#11:
Lack of BMPs at Cattle guard entry.



Photo#12:
Lack of BMPs at Cattle guard entry.

June 27, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Spicer Loc#324754



Photo#13:
Silt fence that has become Debris.

June 27, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Spicer Loc#324754