

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/26/2019

Submitted Date:

07/03/2019

Document Number:

688305043**FIELD INSPECTION FORM**Loc ID 320696 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #210City: AURORA State: CO Zip: 80016**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☐
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Condill, JB	303-680-4725	jbcrog@aol.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204489	WELL	SI	01/01/2019	GW	005-06574	CHAMPLIN 126 AMOCO B 8	SI

**General Comment:**[Bradenhead Test Inspection/Reinspection](#)[Corrective action from 3/6/2019 completed \(see attached photo of tagged out riser\).](#)

**Location**Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	303-680-4725	
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?**Equipment:**

Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	tagged out		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				



**Inspected Facilities**Facility ID: 204489 Type: WELL API Number: 005-06574 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Andarko Third Creek shut in.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Comment: Form 17 is attached. Bradenhead was dead, tubing 0 psi and casing 0 psi.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688305124	Renegade Champlin 126 Amoco B8 Form 17 page 1	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4869223">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4869223</a>
688305125	Renegade Champlin 126 Amoco B8 Form 17 page 2	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4869224">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4869224</a>
688305126	Renegade Champlin 126 Amoco B8 well sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4869225">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4869225</a>
688305127	Renegade Champlin 126 Amoco B8 wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4869231">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4869231</a>
688305128	Renegade Champlin 126 Amoco B8 riser/tagged	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4869232">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4869232</a>