

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/01/2019

Submitted Date:

07/03/2019

Document Number:

688305080**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 320752 Sherman, Susan 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10362Name of Operator: S & D LLCAddress: 7119 SILVER MOON LANECity: FORT COLLINS State: CO Zip: 80525**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Heffner, Taylor	303-219-3362	theffner@phxresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204792	WELL	SI	01/01/2017	GW	005-06877	DANIEL KISSLER 1-9	PA

General Comment:[PA Inspection](#)

LocationOverall Good: ☒**Signs/Marker:**

Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 204792 Type: WELL API Number: 005-06877 Status: SI Insp. Status: PA

CementCement Contractor

Contractor Name: _____

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment: 7/3/20198037' CIBP set by Cutter wireline and 2 sxs bumped on top.

Corrective Action: _____

Date: _____

Workover

Comment: Toby's Oilfield Service Rig 1 MIRU 7/1/2019, 7/2/2019 pulling tubing, running scraper and hydrotesting casing.
7/3/2019 Attempted to set 8037' CIBP on tubing, wouldn't set. Cutter wireline called to set bottom two plugs.

Corrective Action: _____

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688305081	Phoenix PA Rig sign at Manila Rd 7/1/2019	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4869266
688305082	Phoenix PA Rig sign at Cavanaugh Rd 7/1/2019	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4869267
688305083	Phoenix PA Rig 7/1/2019	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4869268
688305134	Phoenix PA Rig Sign 7/3/2019	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4869269
688305135	Phoenix PA Rig 7/3/2019	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4869270