

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/03/2019

Submitted Date:

07/03/2019

Document Number:

689703275**FIELD INSPECTION FORM**

Loc ID 335419	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>				<b>Findings:</b> 8 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262303	WELL	PR	01/08/2002	GW	045-08011	CHEVRON GM44-20	PR
277260	WELL	PR	01/15/2006	GW	045-10657	CHEVRON GM 544-20	PR
277261	WELL	PR	01/23/2006	GW	045-10656	CHEVRON GM 444-20	PR
277262	WELL	PR	01/10/2006	GW	045-10655	CHEVRON GM 343-20	PR

**General Comment:****COGCC Inspection Report Summary**

On Wednesday 07/03/2019 at approximately 1300 hours, I, Inspector Mike Longworth, conducted a field inspection at Terra Rocky Mountain LLC GM44-20, at Location #335419, in Garfield County, Colorado.

While there, I observed Production.

During this inspection the following possible compliance issues were observed:

Bubbling in cellar around well head.

Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

C.A. Date 07/04/2019

Refer to photograph of observed compliance issue.

I spoke with Nate Leonard of TEP via phone to advise of the bubbling around well head GM44-20. He said he said his lead pumper to check it out.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	970-285-9377		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911	
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Plunger Lift	# 4		corrective date
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:	Shared facilities with location 335170 MV 22-20				
Corrective Action:				Date:	

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance



**Inspected Facilities**Facility ID: 262303 Type: WELL API Number: 045-08011 Status: PR Insp. Status: PR**Producing Well**Comment: Bubbling in cellar around well head.Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.Date: 07/04/2019Facility ID: 277260 Type: WELL API Number: 045-10657 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Facility ID: 277261 Type: WELL API Number: 045-10656 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Facility ID: 277262 Type: WELL API Number: 045-10655 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689703276	Inspection 689703275 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4869379">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4869379</a>