

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/14/2019

Submitted Date:

07/07/2019

Document Number:

698600026**FIELD INSPECTION FORM**Loc ID 317043 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10352Name of Operator: CM PRODUCTION LLCAddress: 390 UNION BLVD SUITE 620City: LAKEWOOD State: CO Zip: 80228**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
234897	WELL	PR	01/02/1996	OW	121-07039	OLIVER-WARREN 1	PR

General Comment:

This is an orphaned well inspection. Inspection completed to document progress and completion of equipment decommissioning and removal.

Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program.

See link at end of report for path to downloadable pictures.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Ancillary equipment	# 0		corrective date
Comment:	Remove power control box and pole from wellhead site.		
Corrective Action:		Date:	
Type: Other	# 0		
Comment:	Concrete base for separator busted up and loaded for haul off.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	0	300 BBLS			,	
Comment:	Lay down and load water tank on flatbed trailer for removal.					
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 234897 Type: WELL API Number: 121-07039 Status: PR Insp. Status: PR**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: Well is an Orphaned Well Program well. Flow line disconnected from wellhead. Valves at wellhead are closed and bull plugs installed. Equipment decommissioning, removal and salvage is in progress.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
The CM Production Oliver Warren site equipment decommissioning, removal and salvage task is under way. The Oliver Warren site is the production facility for (1) remote well. Facility consist of (4) 300 BBL tanks, vertical separator with metal shed, and water/oil flow lines/risers. The remote wellhead has a pumping unit with electric prime mover and associated electrical supply equipment.	stjohnw	07/07/2019
Work at site today focused on laying down and loading water tank onto flatbed trailer for haul off. The power control box, pole, and line were pulled and removed from wellhead site. Additionally the concrete separator base was busted up and loaded into side dump for haul off.		

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600027	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4870141