

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/05/2019

Submitted Date:

07/05/2019

Document Number:

696600250**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
312531 \_\_\_\_\_ Wentzel, Dougo \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1401City: DENVER State: CO Zip: 80202**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments2 Number of Corrective Actions

- 
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Burger, Craig		craig.burger@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	<a href="#">All Inspections</a>
Clark, Chris		cogccnotifications@laramie-energy.com	<a href="#">All Inspections</a>
, DNR		dnr_cogccengineering@state.co.us	<a href="#">All Engineering</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221861	WELL	SI	12/01/2018	GW	077-08463	ANDERSON 1	TA

**General Comment:**

[This is a follow up inspection from doc#696600019 Dated 5/3/19](#)

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	970-248-0497 Dispatch 970-242-1234		
Corrective Action:		Date:	
<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	Storage of unused equipment on location. Riser needs Locked Out /Tagged Out		
Corrective Action:	Comply with Rule 603.f .	Date:	08/06/2019
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 221861 Type: WELL API Number: 077-08463 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Temporarily Abandoned  
Wellhead cellar has water in it. Bubbles are seen coming to surface outside of casing, with H2S gas reading at 1.8 ppm and LELS on meter going as high as 9 at time of inspection.  
  
Well had a Braded head test 5/1/19  
Shut in pressure at start 3.5 lbs  
Blew to zero in 10 seconds  
5min 0  
10 min 0  
15 min 0  
20 min 0  
25 min 0  
30 min 0

Corrective Action: [Contact dnr\\_cogccengineering@state.co.us](mailto:dnr_cogccengineering@state.co.us) with resolution plan.

Date: 07/15/2019

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Gradient Terraces	Pass					
		Compaction	Pass			
Gravel	Pass					
		Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>On (Friday) (7/5/19) at approximately (0923), I, Inspector Dougo Wentzel, conducted a (Routine FIU General Field Re-Inspection) at (Laramie) (077-08463), (API #077-08463) in (Mesa) Colorado. While there, I observed (A Production Operation only.) During this inspection compliance issues were observed: Bubbles surfacing from inside of cellar ring around the wellhead. Stored un-used equipment on location. Riser not locked Out / Tagged Out. (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed compliance issue. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. (if correction actions are identified) This is a summary of inspection report.</p>	wentzeld	07/05/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696600251	Inspection 696600250 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4870339">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4870339</a>