

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/08/2019

Submitted Date:

07/08/2019

Document Number:

693500580

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
335697 _____ Silver, Randy _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: _____ 46290 _____
Name of Operator: KP KAUFFMAN COMPANY INC _____
Address: 1675 BROADWAY, STE 2800 _____
City: _____ DENVER _____ State: _____ CO _____ Zip: _____ 80202 _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 _____ Number of Comments
0 _____ Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Lara-Mesa, Susana	303-825-4822	cogcc@kpk.com	All inspections
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275817	WELL	SI	12/01/2018	GW	001-09531	STANDLEY 8-3	SI

General Comment:

Inspected Facilities

Facility ID: 275817 Type: WELL API Number: 001-09531 Status: SI Insp. Status: SI

Complaint

Comment: Inspection in response to complaint.
 Field Inspector Assigned: Randy Silver
 Complaint Received
 Date: 07-03-2019
 Complaint Contacted:
 Date: 07-04-2019 Time: 7-04-19 9:27AM left voice mail.
 Location ID # 335697
 Inspection Document # 693500574
 Complaint Document #200447505
 Nature of Complaint: flaring
 Field Inspector Actions:
 On 07-03-2019, I Randy Silver area field inspector was assigned a complaint received by COGCC staff in reference to flaring.
 On 07-04-2019, I attempted to make contact with the complainant Mark Mellen 2405 East 159th Thornton CO; complainant indicated that on 7-03-19 saw flaring Adjacent to Costco in north Thornton CO. I explained to complainant the operation that rig crew was performing and by flaring, they were controlling the gas when they opened the well to set bridge plug.
 I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection.
 At time of inspection, I spoke with Phip Reyna KPK rig supervisor; he stated they were setting bridge plugs on wells for Interchange frac. Rig crew flared for approx... Two hrs. when they opened the well.
 Weather conditions: Clear
 See inspection document #693500574 per my inspection.
 No violation of COGCC rules were observed at the time of the inspection.
 All information reviewed and site inspection information were submitted to the COGCC for further review.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
See doc#693500574 for full inspection.	silverr	07/08/2019