

Inspection Photos

Loc#458790

Operator: Sandridge

Inspection Number: 692401155

Inspection Date: 6/28/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
View of Location from entry to East.



Photo#2:
Overview of Location from soil stockpile to West.

June 28, 2019



Photo#3:
Area where washout occurred at Northwest corner. Arrow indicating Weir in Photo#4



Photo#4:
Weir installation, at area where washout occurred at Northwest corner.

June 28, 2019



Photo#5:
View of NW washout from bottom of slope and
overwhelmed silt fence.



Photo#6:
Sediment migrating into wetlands; blue flagging
indicates wetlands perimeter.

June 28, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Oxbow Loc#458790



Photo#7:

View along North Fill Slope showing tracking and berm compaction. Insert is area where Silt Fence has been overwhelmed by sediment.

June 28, 2019



Photo#8:
View along stockpile to South.



Photo#9:
View South from top of stockpile over flooded
fields; wattles at base of stockpile in fore ground.

June 28, 2019



Photo#10:
View to North of washout at Northeast corner.



Photo#11:
View from below washout.

June 28, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Oxbow Loc#458790



Photo#12:
Close view of NE washout. Arrow indicates point where water is discharging in Photo#13.



Photo#13:
Point where water from flooded fields is now discharging; channeled according to Operator from French Drain.

June 28, 2019



Photo#14:
Points on access road & berms need installation
of BMPs.



Photo#15:
Points on access road & berms need installation
of BMPs.

June 28, 2019