

# Construction and Stormwater Inspection

July 3, 2019

Operator: BAYSWATER EXPLORATION AND PRODUCTION LLC - #10261

Location ID: 455456

Inspection Document #: 697500289

Weld County, CO

NWNE Section 18 T7N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: EAST AULT 18-C PAD  
Location ID: 455456



**Photo 1.** Photo taken from the northwestern well pad on May 2, 2019, facing North. Operator has not properly stabilized the well pad area to control for dust and erosion per Rule 1002.e.

Inspection Photos  
Location Name: EAST AULT 18-C PAD  
Location ID: 455456



**Photo 2.** Photo taken from the northwestern well pad on May 2, 2019, facing East.  
See comments under Photo 1.



Inspection Photos  
Location Name: EAST AULT 18-C PAD  
Location ID: 455456



**Photo 3.** Photo taken from the western well pad on July 3, 2019, facing East. Operator has failed to properly stabilize the well pad per the previous corrective action inspection. Photo also illustrates the Operator has failed to control and manage weeds throughout the entire well pad.



Inspection Photos  
Location Name: EAST AULT 18-C PAD  
Location ID: 455456



**Photo 4.** Photo taken from the central well pad on July 3, 2019, facing East. The eastern half of the well pad is saturated from irrigation water.



Inspection Photos  
Location Name: EAST AULT 18-C PAD  
Location ID: 455456



**Photo 5.** Photo taken from the north-facing topsoil stockpile on July 3, 2019, facing West. Photo illustrates the Operator has failed to control and manage weeds throughout the entire topsoil stockpile.



Inspection Photos  
Location Name: EAST AULT 18-C PAD  
Location ID: 455456



**Photo 6.** Photo taken from the north-facing topsoil stockpile on July 3, 2019, facing East. See comments under Photo 5.



Inspection Photos  
Location Name: EAST AULT 18-C PAD  
Location ID: 455456



**Photo 7.** Photo taken from the eastern topsoil stockpile on July 3, 2019, facing East. Photo illustrates the Operator has failed to protect the topsoil per Rule 1002.c. Topsoil has been moved to allow the pivot irrigation system to travel through the well pad area.



Inspection Photos  
Location Name: EAST AULT 18-C PAD  
Location ID: 455456



**Photo 8.** Photo taken from the eastern topsoil stockpile on July 3, 2019, facing West. Photo illustrates the Operator has failed to protect the topsoil per Rule 1002.c. and failed to maintain the perimeter stormwater BMPs.



Inspection Photos  
Location Name: EAST AULT 18-C PAD  
Location ID: 455456



**Photo 9.** Photo taken from the western topsoil stockpile on July 3, 2019, facing West. Photo illustrates the Operator has failed to maintain the perimeter stormwater BMPs.