

Caerus Piceance LLC
API # 05-077-08680
Inspection # 696600264



Photo #1 Photo at entrance to location.
Unused equipment on location.
No Battery Sign at entrance or tank battery.



Photo #2 Photo from entrance of location.
No tank battery sign on location.
No Battery Sign at entrance or tank battery.

Caerus Piceance LLC
API # 05-077-08680
Inspection # 696600264



Photo #3 photo of Tank Battery.
No Tank Battery sign on location

Photo #4 Photo at Wellhead

Caerus Piceance LLC
API # 05-077-08680
Inspection # 696600264



Photo #5 Weeds inside tank containment



Photo #6 Weeds inside tank containment

Caerus Piceance LLC
API # 05-077-08680
Inspection # 696600264



Photo #7 Storm water erosion moving sediment off NW corner of location. No BMP or berm needs maintenance



Photo #8 Storm water erosion moving sediment off NW corner of location. No BMP or berm needs maintenance.

Caerus Piceance LLC
API # 05-077-08680
Inspection # 696600264



Photo #9 Un-used equipment on location.