

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/08/2019

Submitted Date:

07/09/2019

Document Number:

687905079**FIELD INSPECTION FORM**
 Loc ID 325330 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 7650Name of Operator: BENSON-MONTIN-GREER DRILLING CORPORATIONAddress: 4900 COLLEGE BLVDCity: FARMINGTON State: NM Zip: 87402**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Stradling, Zak	(505) 324-5074	zstradling@bmgdrilling.com	SW Insp Reports
Labowskie, Steve		steve.labowskie@state.co.us	
Roy, Catherine		catherine.roy@state.co.us	

General Comment:

This site inspection conducted after well PA in regards to form 42 Doc#402064293 that was submitted on 6/4/2019. According to Final tower report from A+ drilling, well was plugged on 6/24/2019 and 90 days to have all equipment removed and flowlines abandoned. Photos at the end of this inspection report.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Above ground dryhole marker installed with well identification information on marker.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:	Wire spools, concrete blocks from separator, toolboxes, nuts and studs at wellhead are all debris.		
Corrective Action:	Remove debris from location per Rule 603.f.	Date:	09/24/2019
Type	UNUSED EQUIPMENT		
Comment:	Chemical injection tank and pump skid, produced water tank, staircase, horizontal separator, valve sets/clusters, piping, electrical equipment are all unused equipment.		
Corrective Action:	Remove unused equipment from location per Rule 603.f.	Date:	09/24/2019
Type	TRASH		
Comment:	Plastic water bottles, foam, pin flags, bent T-posts are all trash.		
Corrective Action:	Remove trash from site per Rule 603.f.	Date:	10/24/2019
Type	UNUSED EQUIPMENT		
Comment:	Flowlines: 2" flowline from wellhead dryhole marker to meter run is not in service.		
Corrective Action:	Remove unused flowlines from location per Rule 603.f.	Date:	09/24/2019
Type	UNUSED EQUIPMENT		
Comment:	Rig anchors are unused equipment.		
Corrective Action:	Remove rig anchors per Rule 1004.a.	Date:	09/24/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Berms	Pass	Compaction	Pass			
Ditches	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905080	UTE #6 Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871614