

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/08/2019

Submitted Date:

07/09/2019

Document Number:

687905081**FIELD INSPECTION FORM**Loc ID 325299 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 7650Name of Operator: BENSON-MONTIN-GREER DRILLING CORPORATIONAddress: 4900 COLLEGE BLVDCity: FARMINGTON State: NM Zip: 87402**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Stradling, Zak	(505) 324-5074	zstradling@bmgdrilling.com	SW Insp Reports
Roy, Catherine		catherine.roy@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214514	WELL	PR	07/27/1976	GW	067-06117	D L GOULD FLUME CANYON 2	PA

**General Comment:**

This site inspection conducted after PA on this location. Form 42 Doc# 402064274 submitted on 6/4/2019. Final daily tower report from A + drilling, shows well was plugged on 6/12/2019 with 90 days to remove all equipment and abandoned flowlines. Photos at the end of this inspection report.

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Dryhole marker with location information at wellhead.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

**Good Housekeeping:**

Type	OTHER		
Comment:	Rig anchors will not be in use with well PA		
Corrective Action:	Remove rig anchors per Rule 1004.a.	Date:	09/12/2019
Type	DEBRIS		
Comment:	Buckets, totes, poly tarps, insulation blankets, laying around produced water tank and separator.		
Corrective Action:	Remove debris per Rule 603.f.	Date:	09/12/2019
Type	UNUSED EQUIPMENT		
Comment:	Produced water tank, separator, compressor piping, valves and wellhead electrical equipment are all unused equipment.		
Corrective Action:	Remove unused equipment per Rule 603.f.	Date:	09/12/2019
Type	TRASH		
Comment:	Pinflags, plastic bottles, foil insulation blanket pieces are all trash.		
Corrective Action:	Clean up trash per Rule 603.f.	Date:	09/12/2019
Type	UNUSED EQUIPMENT		
Comment:	Flowline: Unused 2" flowline piping from wellhead to compressor pad.		
Corrective Action:	Remove unused flowline to Comply with Rule 603.f.	Date:	09/12/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Fail	Ditches	Pass			
Berms	Fail	Compaction	Pass			
Waddles	Fail	Gravel	Pass			

Comment: [Stormwater BMP's along eastern edge of location have channeling under waddles washing silt/gravel offsite.](#)

Corrective Action: [Repair and maintain stormwater BMP'S Per Rule 1002.f.](#)

Date: 08/08/2019

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905082	DL GOULD FLUME CANYON 2 inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871615">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871615</a>