

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/08/2019

Submitted Date:

07/09/2019

Document Number:

687905085**FIELD INSPECTION FORM**
 Loc ID 325351 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**20 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name     | Phone        | Email                       | Comment                               |
|------------------|--------------|-----------------------------|---------------------------------------|
| Inspections, All |              | SanJuanCOGCC@bp.com         | <a href="#">All Inspections</a>       |
| Beebe, Sabre     | 970-779-9398 | Sabre.Beebe@bpx.com         | <a href="#">SW Inspection Reports</a> |
| Labowskie, Steve |              | steve.labowskie@state.co.us |                                       |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 214619      | WELL | PR     | 10/01/1988  | GW         | 067-06223 | CRAIG 1       | PR          |
| 412103      | WELL | PR     | 06/05/2018  | GW         | 067-09732 | CRAIG 3       | PR          |

**General Comment:**[Site inspection with photos at the end of this report.](#)

**Location**Overall Good: ☒

|                      |                                      |       |  |
|----------------------|--------------------------------------|-------|--|
| <b>Signs/Marker:</b> |                                      |       |  |
| Type                 | TANK LABELS/PLACARDS                 |       |  |
| Comment:             | Posted on sign at fence.             |       |  |
| Corrective Action:   |                                      | Date: |  |
| Type                 | WELLHEAD                             |       |  |
| Comment:             | Sign posted at entrance to location. |       |  |
| Corrective Action:   |                                      | Date: |  |

Emergency Contact Number:

Comment: Posted on sign at entrance.

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | WEEDS   |       |            |
| Comment:           | Large amount of Canadian thistle and weeds growing around all production equipment and on location. |       |            |
| Corrective Action: | Control noxious weeds around all equipment and on location per Rule 1003.f. and Rule 603.f.         | Date: | 07/18/2019 |

Overall Good: ☐**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

|                    |   |       |  |
|--------------------|---|-------|--|
| Type               | SEPARATOR   |       |  |
| Comment:           | Cattle panels around separator and produced water tank. |       |  |
| Corrective Action: |   | Date: |  |
| Type               | WELLHEAD  |       |  |
| Comment:           | Cattle panels around wellhead and pumpjack.             |       |  |
| Corrective Action: |   | Date: |  |

**Equipment:**

|                       |                                      |       |                 |
|-----------------------|--------------------------------------|-------|-----------------|
|                       |                                      |       | corrective date |
| Type: Prime Mover     | # 2                                  |       |                 |
| Comment:              | Electric VFD driven motors with MCC. |       |                 |
| Corrective Action:    |                                      | Date: |                 |
| Type: Gas Meter Run   | # 2                                  |       |                 |
| Comment:              | In separator building.               |       |                 |
| Corrective Action:    |                                      | Date: |                 |
| Type: Bird Protectors | # 1                                  |       |                 |
| Comment:              | On produced water tank vent.         |       |                 |
| Corrective Action:    |                                      | Date: |                 |

|                           |  |       |  |
|---------------------------|--|-------|--|
| Type: Submersible Pump    | # 1  |       |  |
| Comment:                  | On produced water tank.  |       |  |
| Corrective Action:        |  | Date: |  |
| Type: Ancillary equipment | # 2  |       |  |
| Comment:                  | Wellheads.   |       |  |
| Corrective Action:        |  | Date: |  |
| Type: Pump Jack           | # 2  |       |  |
| Comment:                  |  |       |  |
| Corrective Action:        |  | Date: |  |
| Type: Vertical Separator  | # 2  |       |  |
| Comment:                  |  |       |  |
| Corrective Action:        |  | Date: |  |
| Type: Flow Line           | # 10   |       |  |
| Comment:                  | 2-4" flowlines from wellhead to separator. 2-2" flowlines from separator blowdown to produced water tank. 2-2" flowlines from separator dump valve to produced water tank. 1-2" flowline from produced water tank transfer pump to offsite gathering system. 2-4" flowlines from separator merging to 1-4" flowline to offsite dogleg. |       |  |
| Corrective Action:        |  | Date: |  |
| Type: Bradenhead          | # 2  |       |  |
| Comment:                  | PVC bradenhead access.   |       |  |
| Corrective Action:        |  | Date: |  |

**Tanks and Berms:**

|                    |  |           |           |         |        |
|--------------------|--|-----------|-----------|---------|--------|
| Contents           | #  | Capacity  | Type      | Tank ID | SE GPS |
| PRODUCED WATER     | 1  | <100 BBLS | PBV STEEL |         | ,      |
| Comment:           | With electric driven transfer pump and level control float switches. |           |           |         |        |
| Corrective Action: |  | Date:     |           |         |        |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

|                    |   |                     |                     |             |
|--------------------|---|---------------------|---------------------|-------------|
| Type               | Capacity  | Permeability (Wall) | Permeability (Base) | Maintenance |
|                    |   |                     |                     |             |
| Comment:           | Double wall tank with no secondary containment. |                     |                     |             |
| Corrective Action: |   | Date:               |                     |             |

**Venting:**

|                    |       |
|--------------------|-------|
| Yes/No             | NO    |
| Comment:           |       |
| Corrective Action: | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 214619 Type: WELL API Number: 067-06223 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Facility ID: 412103 Type: WELL API Number: 067-09732 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |
| Berms            | Pass            | Culverts                | Pass                  |               |                          |         |
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                     | URL   |
|--------------|---------------------------------|---|
| 687905086    | Noxious weeds around equipment. | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871618">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871618</a> |
| 687905087    | Noxious weeds around equipment. | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871619">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871619</a> |
| 687905088    | Mix of weeds around tank.       | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871620">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871620</a> |
| 687905089    | Mix of weeds around wellhead #1 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871621">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871621</a> |
| 687905090    | Mix of weeds around Wellhead #3 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871622">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871622</a> |
| 687905091    | Mix of weeds around Pumpjack.   | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871623">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871623</a> |