

Inspection Photos
Operator: SG Interests
Location/API #: 051-06069
Date: 6-19-2019



Photo 1. View of the northern project area from the northwestern edge facing eastward.



Photo 2. View of erosional channeling and downcutting along the southern edge of the project area. Rock checks do not appear to be functioning.