

Inspection Photos

Loc#445005

Operator: Sandridge

Inspection Number: 692401138

Inspection Date: 6/26/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry.

June 26, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Surprise Loc#445005



Photo#2:
Silt fence overwhelmed.



Photo#3:
Silt fence buried.

June 26, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Surprise Loc#445005



Photo#4:

Points where silt fence is being undercut by stormwater.

Photo#5:

Outside of silt fence where stormwater is daylighting & sediment transporting off site.

June 26, 2019



Photo#6:
Slopes/ topsoil stockpile are not stabilized, resulting in erosion, sediment migration and degradation.



Photo#7:
Slopes/topsoil stockpile are not stabilized, resulting in erosion, sediment migration and degradation.

June 26, 2019



Photo#8:

Weir is not installed in position to function properly.

Photo#9:

Weir is not installed in position to function properly. Arrow indicates where SW is undercutting.

June 26, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Surprise Loc#445005



Photo#10:
Absence of BMPs at entries and along access road.



Photo#11:
Absence of BMPs at entries and along access road.

June 26, 2019