

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate but is starting to fad may need to be replaced in the near future.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	Square tiling		
Corrective Action:		Date:	

Equipment:

Type	Quantity	Comment	Corrective Action	Date	corrective date
Ancillary equipment	# 1	Electric panel			
Pump Jack	# 1				
Bradenhead	# 1	Appears to be plumbed to surface			
Prime Mover	# 1	Electric motor			

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Corrective Action:

Date:

Inspected Facilities

Facility ID: 240071 Type: WELL API Number: 123-07859 Status: PR Insp. Status: PR

Producing Well

Comment: [PR](#)

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
Routine inspection.	silverr	07/09/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693500612	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4872334