

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/09/2019

Submitted Date:

07/09/2019

Document Number:

687905100**FIELD INSPECTION FORM**Loc ID 306822 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10663Name of Operator: ENDURING RESOURCES LLCAddress: 1050 17TH STREET SUITE 2500City: DENVER State: CO Zip: 80265**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**23 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Walter, Kyle		kwalter@enduringresources.com	SW Inspection Reports
Felix, Andrea		afelix@enduringresources.com	All inspections
Pohl, April	505-444-0520	apohl@enduringresources.com	All Inspections Southwest
McDaniel, James	505-444-3004	jmcdaniel@enduringresources.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268969	WELL	PR	12/18/2003	GW	067-08845	MONTOYA 10-3	PR

General Comment:[Site inspection with photos at the end of this report.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign posted at entrance to location.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank labels and placards posted on tanks.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Contact information posted on signs.

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Wind/winter polytarp protection for generator is torn down and blowing around generator and is trash.		
Corrective Action:	Remove trash per Rule 603.f.	Date:	07/19/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	Cattle panels around produced water tank.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Cattle panels around separator and meter run.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panels around wellhead and pumpjack.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Cattle panels around generator.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sound walls around midstream compressor.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Site natural gas generator.		
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:	On separator stack and produced water tank stack.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric VFD drive motor with MCC.		
Corrective Action:			Date:
Type: Flow Line	# 9		
Comment:	1-4" flowline from wellhead to separator. 1-2" flowline from wellhead to separator. 1-2" flowline from separator blowdown to produced water tank. 1-2" flowline from separator dump valve to produced water tank. 1-1" flowline from wellhead to generator fuel gas. 1-1" flowline from separator to produced water tank fuel gas. 1-4" flowline from separator to liquid knockout pot. 1-2" flowline from liquid knockout pot dumpvalve to produced water tank. 1-4" flowline from liquid knockout pot to compressor suction.		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Plumbed to surface.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	268969	Type:	WELL	API Number:	067-08845	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing.								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	Spill prevention for generator oil day tank.
Berms	Pass	Compaction	Pass			
				Material Handling And Spill Prevention	Pass	Spill prevention for chemical injection at well.
Compaction	Pass	Culverts	Pass			
Ditches	Pass	Ditches	Pass			
Gravel	Pass					
Gradient Terraces	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905101	Polytarp trash around generator.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4872932
687905102	Location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4872933
687905103	Location tank battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4872934