

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/09/2019

Submitted Date:

07/09/2019

Document Number:

696300309**FIELD INSPECTION FORM**
 Loc ID 327254 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|--|---------|
| , | | NBL_DJBU_Inspections@NB LENERGY.COM | |
| Kraich, Adam | | adam.kraich@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 246597 | WELL | SI | 06/01/2017 | OW | 123-14394 | HOWARD-BC A 34-02 | SI |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|---|-------|------------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | Tank Battery Sign is missing | | |
| Corrective Action: | Install sign to comply with Rule 210.b. | Date: | 08/12/2019 |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: Emergency Contact Number is missing from location

Corrective Action: Install sign to comply with Rule 210.b.

Date: 08/12/2019

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | WEEDS | | |
| Comment: | Weeds at Tank Battery have overgrown the entire location, see Photo #1 & #2 | | |
| Corrective Action: | Comply with Rule 603.f . | Date: | 07/23/2019 |
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unused equipment at wellhead see photo #7 | | |
| Corrective Action: | Comply with Rule 603.f . | Date: | 07/23/2019 |
| Type | WEEDS | | |
| Comment: | Weeds at Wellhead, see photo #5 & 6 | | |
| Corrective Action: | Comply with Rule 603.f . | Date: | 07/23/2019 |
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unused Tank and stair, walk over stair on location, see photos #2 & #3 | | |
| Corrective Action: | Comply with Rule 603.f . | Date: | 10/11/2019 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|------------------|----------|--|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Panel | | |

| | | |
|---|-----|-----------------|
| Corrective Action: | | Date: |
| Equipment: | | corrective date |
| Type: Bradenhead | # 1 | |
| Comment: Appears to be plumbed to surface | | |
| Corrective Action: | | Date: |
| Type: Horizontal Heated Separator | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Plunger Lift | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Bird Protectors | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Gas Meter Run | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 1 | 300 BBLs | STEEL AST | | 40.446590,-104.534750 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|---|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: No berm on location, Tank has been disconnected. | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | |
|--------------------|-------|
| Yes/No | NO |
| Comment: | |
| Corrective Action: | Date: |

Flaring:

| | |
|----------|--|
| Type | |
| Comment: | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Inspected FacilitiesFacility ID: 246597 Type: WELL API Number: 123-14394 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: TA, MIT Test Failed on 05.04.2019 per form 21 Doc ID 402032492

Corrective Action: _____ Date: _____

COGCC Comments

| Comment | User | Date |
|---|--------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Tuesday at approximately 11:26 AM, I, Inspector Erica Petrie, conducted a Field Inspection at Noble Energy INC, Howard BC A 34-02, at Location #327254 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds at Tank Battery, see photos 1 & 2, comply with Rule 603.f, Corrective Action date of 07.23.2019</p> <p>Weeds at Wellhead, see photos 5 & 6, comply with Rule 603.f, Corrective Action date of 07.23.2019</p> <p>Unused Tank, Stairs, and walk over stairs, see photos 2 & 3, comply with Rule 603.f, Corrective Action date of 10.11.2019</p> <p>Unused Wellhead parts and fittings at Wellhead, see photo 7, comply with Rule 603.f, Corrective Action date of 07.23.2019</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> | petrie | 07/09/2019 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 696300310 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4872949 |