

Inspection Photos
Location Name: LORENCITO 12-9-34-66
API#: 05-071-06654
INSP. #: 695100988



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN

Inspection Photos

Location Name: LORENCITO 12-9-34-66

API#: 05-071-06654

INSP. #: 695100988



PHOTO 3: EROSION IN DITCH ALONG ACCESS ROAD NORTH OF LOCATION. REPAIR EROSION, INSTALL BMP'S AND MAINTAIN IN ACCORDANCE WITH 1002.f. CA DATE 8/9/19.



PHOTO 4: EROSION IN DITCH ALONG ACCESS ROAD NORTH OF LOCATION. REPAIR EROSION, INSTALL BMP'S AND MAINTAIN IN ACCORDANCE WITH 1002.f. CA DATE 8/9/19.

Inspection Photos

Location Name: LORENCITO 12-9-34-66

API#: 05-071-06654

INSP. #: 695100988



PHOTO 5: IMPACTED SOIL UNDER PUMPJACK PRIME MOVER AND GEAR BOX. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 8/9/19