

Inspection Photos

API: 05-009-06555

Operator: LORENTZ OIL & GAS

Inspection Date: 7/9/2019



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06555 | Date: 7/9/2019

Inspection Photos



Photo 1. Facing south along the former access road. Crop is stunted and has not reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06555 | Date: 7/9/2019

Inspection Photos



Photo 2. Facing south toward the location. Crop has not reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06555 | Date: 7/9/2019

Inspection Photos




Photo 3. Facing north toward the location. Crop has not reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06555 | Date: 7/9/2019

Inspection Photos



Photo 4. Facing northeast toward the location. Crop is stunted and has not reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06555 | Date: 7/9/2019

Inspection Photos



Photo 5. There is a pipe riser that remains on the north side of the county road approximately 2700' to the northeast of the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06555 | Date: 7/9/2019

Inspection Photos



Photo 6. There is a pipe riser and meter shed that remains on the south side of the county road approximately 2700' to the northeast of the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06555 | Date: 7/9/2019

Inspection Photos



Photo 7. Sign that remains at the meter shed shown in previous picture.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06555 | Date: 7/9/2019