

Inspection Photos

API: 05-009-06643

Operator: CHOLLA PRODUCTION

Inspection Date: 7/9/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06643 | Date: 7/9/2019

Inspection Photos



Photo 1. Facing north at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06643 | Date: 7/9/2019

Inspection Photos



Photo 2. Facing west at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06643 | Date: 7/9/2019

Inspection Photos



Photo 3. Facing south at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06643 | Date: 7/9/2019

Inspection Photos



Photo 4. Facing east at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06643 | Date: 7/9/2019

Inspection Photos



Photo 5. View of vegetation cover at the location consists of weedy species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06643 | Date: 7/9/2019

Inspection Photos



Photo 6. There is a pipe riser 150' west of the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06643 | Date: 7/9/2019

Inspection Photos



Photo7. Surrounding reference area consists of Common sunflowers.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06643 | Date: 7/9/2019