

Inspection Photos  
Operator: Kinder Morgan  
Location/API #: 033-06081  
Date: 7-1-2019



Photo 1. View of course rock run-down within the southern project area, appears newly installed.



Photo 2. View of rock placement along the western edge of the well pad above eroding slopes. This appears newly installed and will require monitoring as well pad slopes southwestward.





Photo 3. View of dalmatian toadflax (yellow flowers; *Linaria dalmatica*) within the western project area.