

Caerus Piceance LLC
API # 05-077-09079
Inspection # 696600286



Photo #1. Photo at entrance of location.

Photo #2 Photo at entrance of location.

Caerus Piceance LLC
API # 05-077-09079
Inspection # 696600286



Photo #3. Photo of tank battery



Photo #4 photo Separator

Caerus Piceance LLC
API # 05-077-09079
Inspection # 696600286



Photo #5 photo of holes in tank containment liner



Photo #6 photo of holes in tank containment liner

Caerus Piceance LLC
API # 05-077-09079
Inspection # 696600286



Photo #7 photo of holes in containment liner



Photo #8 Erosion leading to a hole on location

Caerus Piceance LLC
API # 05-077-09079
Inspection # 696600286



Photo #9 Erosion leading to a hole on location



Photo #10 Storm water BMP need maintenance. Drain is full of sediment.

Caerus Piceance LLC
API # 05-077-09079
Inspection # 696600286



Photo #11 Deadman not marked



Photo #12 Deadman not marked