

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/26/2019

Submitted Date:

07/11/2019

Document Number:

698600060

FIELD INSPECTION FORM

Loc ID 317289 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 27635
Name of Operator: ENERGY SEARCH CO ADBA ENERGY SEARCH CO
Address: PO BOX 1896
City: EDWARDS State: CO Zip: 81632

Findings:

- 14 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
237842	WELL	PR	02/19/2015	OW	121-10345	RESLER 22-27	TA

General Comment:

This is an orphaned well inspection. Inspection completed to document progress and completion of equipment decommissioning and removal.

Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program.

See link at end of report for path to downloadable pictures.

Location				
Lease Road:				
	Type Access			
	comment: Access to well by dirt two track road off maintained county road.			
Corrective ActionL				Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
	Type WELLHEAD			
	Comment:			
Corrective Action:				Date:
Emergency Contact Number:				
	Comment: COGCC contact sticker.			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
	Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
	Type PUMP JACK			
	Comment: Steel safety rail barrier.			
Corrective Action:				Date:
	Type WELLHEAD			
	Comment: Wire and post fencing			
Corrective Action:				Date:
Equipment:				
Type: Other	# 1			corrective date
	Comment: Prime mover shed. Shed removed from over prime mover and sat on edge of location.			
Corrective Action:				Date:
Type: Deadman # & Marked	# 4			
	Comment: Located (4) marked anchors.			
Corrective Action:				Date:
Type: Flow Line	# 1			
	Comment: 3" steel line from wellhead to remote separator on Resler 12-27 production facility.			
Corrective Action:				Date:
Type: Prime Mover	# 1			
	Comment: Natural gas motor.			
Corrective Action:				Date:

Type: Ancillary equipment	# 1		
Comment:	Chemical tank and pump in secondary containment.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 237842 Type: WELL API Number: 121-10345 Status: PR Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well is an Orphaned Well Program well. Valves at wellhead are closed. Equipment decommissioning, removal and salvage is in progress.

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>The Energy Search Resler Site equipment decommissioning, removal and salvage task is under way. The Resler production facility consist of (2) 300 BBL tanks, (1) 100 BBL concrete sump, skim pit, production pit, vertical separator with metal shed, pumping unit with metal shed, and water/oil flow lines/risers. Production facility also services (1) remote well the Rasler 22-27.</p> <p>Work at site today started around the wellhead area. The prime mover shed was removed from over the prime mover and relocated to the edge of location.</p>	stjohnw	07/11/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600061	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4875344