

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/11/2019

Submitted Date:

07/11/2019

Document Number:

687905121**FIELD INSPECTION FORM**
 Loc ID 311958 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
,	970-563-4000	maralextech@gmail.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277813	WELL	PR	01/10/2006	GW	067-09049	MARY CATHERINE 33-7-3 2A	PR
294238	WELL	PR	05/11/2008	GW	067-09476	MARY CATHERINE 33-7-3 3C	PR

**General Comment:**

This is a follow up inspection of this location from prior inspection doc#687904777. This inspection does not allieviate corrective actions from prior inspection. Completed corrective actions will be noted in this inspection report. Photos are at the end of this inspection report.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds have been removed from around equipment.		
Corrective Action:		Date:	
Type	UNUSED EQUIPMENT		
Comment:	Unused wellhead valve that was sitting on pumpjack has been removed.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Pump Jack	# 2		corrective date
Comment:	33-7-3 #2A and #3C both have gearbox seal leaks on pumpjack and stained soil and oily waste are present along concrete. Corrective action has not been completed from previous inspection.		
Corrective Action:	Comply with Rule 605.d. and Rule 907.e.		Date: 06/14/2019
Type: Ancillary equipment	# 1		
Comment:	Wellhead has localized areas of stained soil and gravel and oily waste. Treat and dispose of properly. Corrective action has not been completed from previous inspection.		
Corrective Action:	Comply with Rule 907.e. and Rule 1002.f.(2)		Date: 06/16/2019

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 277813 Type: WELL API Number: 067-09049 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Facility ID: 294238 Type: WELL API Number: 067-09476 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Fail	

Comment: Pump jack engine oil day tanks do not have spill prevention. Implement and maintain Best Management Practices (BMP's) to include measures such as spill prevention. Corrective action has not been completed since last inspection.

Corrective Action: **Comply with Rule 1002.f.(2)B**

Date: 06/16/2019

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905122	Weeds removed	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876056">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876056</a>
687905123	No spill prevention	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876057">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876057</a>
687905124	Gearbox leak	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876058">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876058</a>
687905125	wellhead valve removed from pumpjack skid.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876059">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876059</a>
687905126	Stained soil/gravel	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876060">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876060</a>
687905127	Gearbox leak.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876061">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876061</a>