

Inspection Photos

API: 05-071-06598

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/11/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-06598 | Date: 7/11/2019

Inspection Photos



Photo 1. Facing along the main road. Rock rip/rap has been installed as outlet protection at numerous culvert outlets.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06598 | Date: 7/11/2019

Inspection Photos



Photo 2. Facing along the main road. Rock rip/rap has been installed as outlet protection at numerous culvert outlets.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06598 | Date: 7/11/2019

Inspection Photos



Photo 3. Outlet protection has been installed on the culvert with geotextile.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06598 | Date: 7/11/2019

Inspection Photos



Photo 4. Rip/rap has been installed along the side of the road where erosion was occurring.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06598 | Date: 7/11/2019

Inspection Photos



Photo 5. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06598 | Date: 7/11/2019