

**Inspection Photos**  
**Location Name: STATE-68N60W /36SESE**  
**Location #: 331563**



**Photo #1**  
**State 36-16 (05-123-20908) Wellsite**  
**Shut-In | SI**  
*Day tanks, drum removed*  
*Stained soil appears mitigated*

**Photo #2**  
**State 36-16 Battery**  
**Shut-down**

**Inspection Photos**  
**Location Name: STATE-68N60W /36SESE**  
**Location #: 331563**



**Photo #3**  
**State 36-16** Wellsite  
*Sign posted*




**Photo #4**  
**State 36-16** Battery sign  
*Phone number illegible – prior insp.*

**Inspection Photos**  
**Location Name: STATE-68N60W /36SESE**  
**Location #: 331563**



**Photo #5**  
**State 36-16 Battery sign**  
**Phone number is Legible**  
**See Photo #6**



**Photo #6**  
**State 36-16 Battery sign**  
**Phone number is Legible**  
**Sign adjacent to walkway sign**

**Inspection Photos**  
**Location Name: STATE-68N60W /36SESE**  
**Location #: 331563**



**Photo #7**  
**State 36-16** Wellsite  
*Access road ruts - Appears mitigated*



**Photo #8**  
**State 36-16** Battery – Oil Tanks  
**2 – Unmarked, Unused risers**

**Inspection Photos**  
**Location Name: STATE-68N60W /36SESE**  
**Location #: 331563**



**Photo #9**  
**State 36-16 Prime Mover – Gas Engine**  
**Stained soil beneath gas engine**  
*prior insp.*



**Photo #10**  
**State 36-16 Prime Mover – Gas Engine**  
**Stained soil beneath gas engine**  
*Appears mitigated*

**Inspection Photos**  
**Location Name: STATE-68N60W /36SESE**  
**Location #: 331563**



**Photo #11**  
**State 36-16** Crude Oil Tanks – East side  
**Stained soil**  
*prior insp.*



**Photo #12**  
**State 36-16** Crude Oil Tanks – East side  
**Stained soil - *Appears mitigated***

**Inspection Photos**  
**Location Name: STATE-68N60W /36SESE**  
**Location #: 331563**



**Photo #13**  
**State 36-16** Treater – Separator shed  
**Stained soil**  
*prior insp.*



**Photo #14**  
**State 36-16** Treater – Separator shed  
**Stained soil - *Appears mitigated***

**Inspection Photos**  
**Location Name: STATE-68N60W /36SESE**  
**Location #: 331563**



**Photo #15**  
**State 36-16** Crude Oil Tanks – Front Load outs  
**Stained soil**  
*prior insp.*



**Photo #16**  
**State 36-16** Crude Oil Tanks – Front Load outs  
**Stained soil - *Appears mitigated***

**Inspection Photos**  
**Location Name: STATE-68N60W /36SESE**  
**Location #: 331563**



**Photo #17**

**State 36-16** Crude Oil Tanks – Rear drain valves  
**Stained soil**  
*prior insp.*

**Photo #18**

**State 36-16** Crude Oil Tanks – Rear drain valves  
**Stained soil - *Appears mitigated***

**Inspection Photos**  
**Location Name: STATE-68N60W /36SESE**  
**Location #: 331563**



**Photo #19**  
**State 36-16** Pit Area – Skim tank  
**No NFPA placard**  
*prior insp.*



**Photo #20**  
**State 36-16** Pit Area – Skim tank  
**NFPA placard - Posted**

**Inspection Photos**  
**Location Name: STATE-68N60W /36SESE**  
**Location #: 331563**



**Photo #21**  
**State 36-16 Pit Area**  
**Damaged berms, stain soil, netting gaps**  
*prior insp.*



**Photo #22**  
**State 36-16 Pit Area**  
**Damaged berms, stain soil, netting gaps**  
*prior insp.*

**Inspection Photos**  
**Location Name: STATE-68N60W /36SESE**  
**Location #: 331563**



**Photo #23**  
**State 36-16 Pit Area**  
**Damaged berms, stain soil, netting gaps**  
*Appears mitigated.*



**Photo #24**  
**State 36-16 Pit Area**  
**Damaged berms, stain soil, netting gaps**  
*Appears mitigated*

**Inspection Photos**  
**Location Name: STATE-68N60W /36SESE**  
**Location #: 331563**



**Photo #25**  
**State 36-16** Produced H2O tanks  
**Inadequate berms**  
*prior insp.*



**Photo #26**  
**State 36-16** Produced H2O tanks  
**Enlarged berms**  
*Appears mitigated*

**Inspection Photos**  
**Location Name: STATE-68N60W /36SESE**  
**Location #: 331563**



**Photo #27**  
**State 36-16** Produced Oil tanks  
**Inadequate berms**  
*prior insp.*



**Photo #28**  
**State 36-16** Produced Oil tanks  
**Enlarged berms**  
*Appears mitigated*