

Inspected Facilities

Facility ID: 217795 Type: WELL API Number: 071-06574 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Ditches	Fail			

Comment: PHOTO 3: AREA OF EROSION ON MAIN ROW NORTH OF LOCATION TOWARD THE BOTTOM OF THE HILL.
 PHOTO 4: CLOSER VIEW OF EROSION FROM PREVIOUS PHOTO (PHOTO 3).

Corrective Action: REPAIR EROSION AND REPAIR OR INSTALL BMP'S TO PREVENT EROSION AND COMPLY WITH RULE 1002.f.

Date: 09/12/2019

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695101043	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4877594