

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/09/2019

Submitted Date:

07/12/2019

Document Number:

680305218**FIELD INSPECTION FORM**
 Loc ID 312139 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 35190Name of Operator: GRAYHORSE OPERATING INCAddress: 20 EAST 5TH ST STE 320City: TULSA State: OK Zip: 74103**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Crumley, Tim	(970)768-5659	tcrumley@centurytel.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
218811	WELL	IJ	05/01/2000	DSPW	075-05562	HOXIE 2 WD	WK

General Comment:

WO - Workover Inspection IJ well. Summary to date: 07/08/2019 Operator is in process of assessing repairs following UIC/MIT failure Doc# 680305106 performed on 6/10/2019. Operator has (6) months to repair and return to service or plug the well commencing on date of FIR on 6/10/2019.

Location

Lease Road:			
Type	Access		
comment:	Across dryland wheat (planted) from Ct. Rd. 27 to wellhead.		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Satisfactory		
Corrective Action:		Date:	

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Heavy welded wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 0		
Comment:	No change in equipment inventoried.		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 218811 Type: WELL API Number: 075-05562 Status: IJ Insp. Status: WK**Workover**

Comment: Summary of WO: (7/1/2019 - 7/8/2019). MIRU. Safety meetings with daily work plan. Initial difficulty releasing packer, pulled tubing, tripped tubing setting packer and testing, resetting packer and testing to locate leak, process repeated several times, well did not hold/test as of date of this FIR. Origin of pressure loss @ MIT, undetermined as of date of this FIR.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	In Process	Other	In Process			

Comment: [Located within rotational cropland w/rotational tillage.](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
IJ well workover in progress.	schureky	07/12/2019