

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/09/2019

Submitted Date:

07/12/2019

Document Number:

680305219**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
312139 SCHURE, KYM 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 35190Name of Operator: GRAYHORSE OPERATING INCAddress: 20 EAST 5TH ST STE 320City: TULSA State: OK Zip: 74103**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Crumley, Tim	(970)768-5659	tcrumley@centurytel.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
218811	WELL	IJ	05/01/2000	DSPW	075-05562	HOXIE 2 WD	WK

**General Comment:**

WO Inspection UIC/IJ 2019. WO progressing in attempt to locate leak per Doc#680305106.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Across existing wheat field, two track.		
Corrective Action:		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Satisfactory		
Corrective Action:		Date:	

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Heavy welded wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Other	# 0		
Comment:	No change to equipment inventoried.		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 218811 Type: WELL API Number: 075-05562 Status: IJ Insp. Status: WK**BradenHead**Comment: Release pressure. Immediate blow down.

Corrective Action:

Date: \_\_\_\_\_

**Workover**Comment: Safety meeting with daily work plan, tripping tubing and resetting/moving packer to locate leak. Leak source undetermined as of date of this FIR. WO process continues.

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	In Process	Other	In Process			

Comment: [Located within dryland cropland with rotational tillage.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">WO on IJ well leak per Doc#680305106</a>	schureky	07/12/2019