

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/15/2019

Submitted Date:

07/15/2019

Document Number:

687905153**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 325589      Stewart, Joseph      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 96735Name of Operator: WILLIFORD RESOURCES, L.L.C.Address: 6506 S LEWIS AVE STE 102City: TULSA      State: OK      Zip: 74136**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Stevens, Glenn	(970) 749-0192	glennstevens@centurylink.net	
Labowskie, Steve		steve.labowskie@state.co.us	
Callahan, Linda	(918) 712-8828	lcallahan3@swbell.net	<a href="#">e-mail receipient</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215051	WELL	PR	03/01/2019	OW	067-06656	SCHMITT ESTATE 2-36	PR

**General Comment:**[This is a site inspection with photos at the end of this report.](#)

Location					
<b>Lease Road:</b>					
Type	Access				
comment:	Two track dirt road across private property.				
Corrective Action	L				Date:
Overall Good: <input type="checkbox"/>					
<b>Signs/Marker:</b>					
Type	WELLHEAD				
Comment:	Sign posted at wellhead.				
Corrective Action:					Date:
Emergency Contact Number:					
Comment:	Emergency contact information and 911 posted on sign.				
Corrective Action:					Date: _____
<b>Good Housekeeping:</b>					
Type	WEEDS				
Comment:	Weeds are overgrown around pumping unit.				
Corrective Action:	Remove weeds to comply with Rule 603.f.				Date: 07/25/2019
Overall Good: <input type="checkbox"/>					
<b>Spills:</b>					
Type	Area	Volume			
In Containment: No					
Comment: _____					
<input type="checkbox"/> Multiple Spills and Releases?					
<b>Fencing/:</b>					
Type	PUMP JACK				
Comment:	Hog panels around wellhead and pumpjack.				
Corrective Action:					Date:
<b>Equipment:</b>					
					corrective date
Type: Ancillary equipment	# 1				
Comment:	Wellhead has stained soil from oily waste around it.				
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.				Date: 08/15/2019
Type: Pump Jack	# 1				
Comment:	Pumpjack engine is leaking engine oil and staining soil around it.				
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e. and Rule 605.d.				Date: 08/15/2019
Type: Flow Line	# 2				
Comment:	1-2" flowline from wellhead to centralized tank battery. 1-1" flowline from wellhead to pumpjack engine fuel gas.				
Corrective Action:					Date:
<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS

CRUDE OIL	2	300 BBLS	STEEL AST		,	
Comment: NFPA labeling on centralized tank battery is not legible.						
Corrective Action: Replace labels on tanks per Rule 210.d.						Date: 08/15/2019
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:						Date:

<b>Inspected Facilities</b>				
Facility ID: 215051	Type: WELL	API Number: 067-06656	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing.			
Corrective Action:				Date:

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Ditches	Pass	Culverts	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905163	Oil leak from engine/stained soil.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879066">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879066</a>
687905164	Stained soil around wellhead.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879067">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879067</a>
687905165	Weeds around equipment.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879068">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879068</a>
687905166	Labeling on tank battery.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879069">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879069</a>