

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/15/2019

Submitted Date:

07/15/2019

Document Number:

687905158**FIELD INSPECTION FORM**

Loc ID 325326 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96735Name of Operator: WILLIFORD RESOURCES, L.L.C.Address: 6506 S LEWIS AVE STE 102City: TULSA State: OK Zip: 74136**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments5 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Stevens, Glenn	(970) 749-0192	glennstevens@centurylink.net	
Callahan, Linda	(918) 712-8828	lcallahan3@swbell.net	e-mail receipient

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214567	WELL	PR	03/01/2011	OW	067-06170	SPRING HOLLOW MAC 1	PR

General Comment:

[Site inspection with photos at the end of this report.](#)

Location			
Lease Road:			
Type	Access		
comment:	Two-track dirt road.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign posted at wellhead.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Contact information and 911 posted on sign.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused 400BBL tank sitting on location and disconnected from process. Secondary containment berm is inadequate. Tank is unused equipment.		
Corrective Action:	Remove unused equipment from location per Rule 603.f.		Date: <u>10/15/2019</u>
Type	WEEDS		
Comment:	Weeds around pumpjack.		
Corrective Action:	Control weeds around equipment per Rule 603.f.		Date: <u>07/25/2019</u>
Type	TRASH		
Comment:	Used belts and hose are trash.		
Corrective Action:	Remove trash from location per Rule 603.f.		Date: <u>07/25/2019</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Pump Jack	# 1		corrective date
Comment:	Pumpjack gearbox leaking and staining soil.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: <u>08/15/2019</u>
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:			Date:
Type: Flow Line	# 2		
Comment:	1-2" flowline from wellhead to centralized crude oil tank battery. 1-1" flowline from wellhead to unknown delivery point. Pumpjack powered be electric motor and not natural gas.		

Corrective Action:	Date:
--------------------	-------

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLs	STEEL AST		

Comment: Tank is not currently connected to process and has open drain plug in the bottom of it.
 Tank is unused equipment, see Corrective action under housekeeping.

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate

Comment: Inadequate berms around tank. Tank not in use.

Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1).	Date: 08/15/2019
---	------------------

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 214567 Type: WELL API Number: 067-06170 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Ditches	Pass	Culverts	Pass			

Comment: Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT
Attached Documents
 You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905176	Trash and weeds around pumpjack.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879079
687905177	Leaking gearbox and stained soil.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879080
687905178	Open end on tank. Disconnected from process, not in use.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879081
687905179	Inadequate secondary containment/Weeds	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879082