

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/15/2019

Submitted Date:

07/15/2019

Document Number:

687905162**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 325540      Stewart, Joseph      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 96735Name of Operator: WILLIFORD RESOURCES, L.L.C.Address: 6506 S LEWIS AVE STE 102City: TULSA      State: OK      Zip: 74136**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Callahan, Linda	(918) 712-8828	lcallahan3@swbell.net	<a href="#">e-mail receipient</a>
Labowskie, Steve		steve.labowskie@state.co.us	
Stevens, Glenn	(970) 749-0192	glennstevens@centurylink.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214975	WELL	PR	02/01/2019	GW	067-06580	HARRIS, RUSSELL 1	PR

**General Comment:**[Site inspection with photos at the end of this report.](#)

Location					
<b>Lease Road:</b>					
Type	Access				
comment:	Two-track dirt road.				
Corrective Action	L				Date:
Overall Good: <input type="checkbox"/>					
<b>Signs/Marker:</b>					
Type	TANK LABELS/PLACARDS				
Comment:	Tank labels and placards are falling off or disintegrated.				
Corrective Action:	Install sign to comply with Rule 210.e.				Date: 08/15/2019
Type	WELLHEAD				
Comment:	Sign posted at wellhead.				
Corrective Action:					Date:
Emergency Contact Number:					
Comment:	Emergency contact information and 911 posted on sign.				
Corrective Action:					Date: _____
Overall Good: <input type="checkbox"/>					
<b>Spills:</b>					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
<b>Equipment:</b>					
Type: Ancillary equipment	# 1				corrective date
Comment:	Wellhead has stained soil around it.				
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.				Date: 08/15/2019
Type: Pump Jack	# 1				
Comment:	Pumpjack in broken and currently not operable.				
Corrective Action:	Inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.				Date: 08/15/2019
Type: Flow Line	# 2				
Comment:	1-2" flowline from wellhead to centralized crude oil tank battery. 1-1" flowline from wellhead to pumpjack engine fuel gas.				
Corrective Action:					Date:
<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		,
Comment:	See corrective action under tanks/labels.				
Corrective Action:					Date:
<b>Paint</b>					

Inspector Name: Stewart, Joseph

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	214975	Type:	WELL	API Number:	067-06580	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing.								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Ditches	Pass	Culverts	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905183	Broken down pumpjack.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879086">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879086</a>
687905184	Stained soil around wellhead.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879087">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879087</a>
687905185	Inadequate labeling on tanks.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879088">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879088</a>
687905186	Inadequate labeling on tanks.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879089">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879089</a>