

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/15/2019

Submitted Date:

07/15/2019

Document Number:

689703329**FIELD INSPECTION FORM**Loc ID 335457 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268848	WELL	PR	02/17/2004	OW	045-09304	CHEVRON GM 332-20	PR
268909	WELL	PR	07/30/2003	OW	045-09312	CHEVRON GM 333-20	PR
283747	WELL	PR	08/09/2006	GW	045-11986	CHEVRON GM 422-20	PR
283748	WELL	PR	08/13/2006	GW	045-11987	CHEVRON GM 532-20	PR
283749	WELL	PR	03/10/2006	GW	045-11988	CHEVRON GM 432-20	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities						
Facility ID:	268848	Type:	WELL	API Number: 045-09304	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	268909	Type:	WELL	API Number: 045-09312	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	283747	Type:	WELL	API Number: 045-11986	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	283748	Type:	WELL	API Number: 045-11987	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well					
Corrective Action:						Date:
Facility ID:	283749	Type:	WELL	API Number: 045-11988	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well					
Corrective Action:						Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
Gravel	Pass					
		Gravel	Pass			
		Compaction	Pass			
		Ditches	Pass			
Compaction	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689703330	Inspection 689703329 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879191