

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/08/2019

Submitted Date:

07/09/2019

Document Number:

687905079

**FIELD INSPECTION FORM**

Loc ID 325330 Inspector Name: Stewart, Joseph On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 7650  
Name of Operator: BENSON-MONTIN-GREER DRILLING CORPORATION  
Address: 4900 COLLEGE BLVD  
City: FARMINGTON State: NM Zip: 87402

**Findings:**

- 8 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Roy, Catherine		catherine.roy@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
Stradling, Zak	(505) 324-5074	zstradling@bmgdrilling.com	SW Insp Reports

**General Comment:**

This site inspection conducted after well PA in regards to form 42 Doc#402064293 that was submitted on 6/4/2019. According to Final tower report from A+ drilling, well was plugged on 6/24/2019 and 90 days to have all equipment removed and flowlines abandoned. Photos at the end of this inspection report.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Above ground dryhole marker installed with well identification information on marker.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Chemical injection tank and pump skid, produced water tank, staircase, horizontal separator, valve sets/clusters, piping, electrical equipment are all unused equipment.		
Corrective Action:	Remove unused equipment from location per Rule 603.f.	Date:	09/24/2019
Type	UNUSED EQUIPMENT		
Comment:	Flowlines: 2" flowline from wellhead dryhole marker to meter run is not in service.		
Corrective Action:	Remove unused flowlines from location per Rule 603.f.	Date:	09/24/2019
Type	UNUSED EQUIPMENT		
Comment:	Rig anchors are unused equipment.		
Corrective Action:	Remove rig anchors per Rule 1004.a.	Date:	09/24/2019
Type	TRASH		
Comment:	Plastic water bottles, foam, pin flags, bent T-posts are all trash.		
Corrective Action:	Remove trash from site per Rule 603.f.	Date:	10/24/2019
Type	DEBRIS		
Comment:	Wire spools, concrete blocks from separator, toolboxes, nuts and studs at wellhead are all debris.		
Corrective Action:	Remove debris from location per Rule 603.f.	Date:	09/24/2019

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		

Corrective Action:

Date:



**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Gravel	Pass			
Berms	Pass	Compaction	Pass			
Compaction	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402099607	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871644">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871644</a>
687905080	UTE #6 Inspection photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871614">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871614</a>