

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/18/2019

Submitted Date:

07/09/2019

Document Number:

693900458

FIELD INSPECTION FORM

Loc ID 428197 Inspector Name: ROY, CATHERINE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 77330
Name of Operator: SG INTERESTS I LTD
Address: 100 WAUGH DR SUITE 400
City: HOUSTON State: TX Zip: 77007

Findings:

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		inspection@sginterests.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
428196	WELL	PR	05/01/2018	SI	051-06107	ECK 12-90-1 1	RI
431411	WELL	XX	03/15/2017	LO	051-06113	Eck WDW 2	RI
431413	WELL	XX	01/03/2017	LO	051-06114	Eck 12-90-1 3	RI

General Comment:

This is a reclamation and stormwater inspection. Document 401293481 is a delayed interim reclamation variance for this location. If delayed operations are no longer needed, then interim reclamation should be conducted. 051-06113 is an expired permit on this location, and needs to be filed as an abandoned location or an updated permit. A pending Form 2 is on file for the 051-06114 well.

Inspected Facilities

Facility ID: 428196 Type: WELL API Number: 051-06107 Status: PR Insp. Status: RI

Facility ID: 431411 Type: WELL API Number: 051-06113 Status: XX Insp. Status: RI

Facility ID: 431413 Type: WELL API Number: 051-06114 Status: XX Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: OTHER, RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Fail

Comment Unused equipment and wood debris stored on the well pad around the wellhead.

Corrective Action Remove and properly store unused equipment and debris.

Date 08/05/2019

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment Well pad cut-slopes remain sparsely vegetated. Revegetation within the project fill slopes appears to be progressing. See attached photos.

Corrective Action Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<p>Comment: Slope stabilization blanket on the well pad cut-slope is failed and needs to be repaired or replaced. Erosion is occurring along the majority of the length of the access road where sediment from road fill is placed down slope and washing into the adjacent stream. Cut slopes for road are not stabilized, culverts are damaged and full of sediment. Rock rundowns are not properly installed and sediment is accumulating on and around rocks. Erosional downcutting is occurring along the roadside ditches. Lastly, stormwater is ponding on the well pad.</p>						<p>Date: 07/22/2019</p>
<p>Corrective Action: Stormwater controls need to be installed to stabilize erosion along the well pad, access road ditches, and bare soils downslope from the road. Culverts need to be repaired/replaced as needed. Erosional blanket on well pad cut-slopes needs to be repaired or replaced. Stormwater controls need to be installed using good engineering practices such as those described in CDOT stormwater and erosion manuals. This is the second corrective action for stormwater erosion at this location.</p>						
<p>Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402099704	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871768
693900475	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871765