

Inspection Photos
Operator: BP America
Location/API #: 067-07114
Date: 7-10-2019



Photo 1. View of the southern project area from the southwestern corner facing eastward.



Photo 2. View of musk thistles (*Carduus nutans*) within the project area.



Photo 3. View of erosional channel in northern project area that is eroding the northern cut-slope.



Photo 4. View of Russian knapweed (*Rhaponticum repens*) within the northern project area. Northern cut-slope is not stabilized.