

**Inspection Photos**  
**Location Name: SINJIN-66N65W /36SWSW**  
**Location #: 328688**



**Photo #1**

**Sinjin E 36-13 (API # 05-123-16306) Wellsite**  
**Temporarily Abandoned | TA**  
*No LOTO on Master / Casing valves*  
*No LTSI or Decommission TA/SI tags per agreement*  
*Unused Equipment – prior insp.*



**Photo #2**

**Sinjin E 36-13 Wellsite**  
**Temporarily Abandoned | TA**  
***LOTO NOW on Master / Casing valves***  
***LTSI or Decommission TA/SI tags NOW posted***  
***Unused Equipment – Removed***

## Inspection Photos

Location Name: SINJIN-66N65W /36SWSW

Location #: 328688



Colorado Oil & Gas Conservation Commission  
40.43519, -104.61144, 1391.0m, 329°  
05/31/2019 03:04:18 PM

### Photo #3

Sinjin E 36-9, 11, 12, 13, 25, LDS F 1-29 Battery

Shut-down

*Mud w/ puddles from prior rain  
prior insp.*



Colorado Oil & Gas Conservation Commission  
40.43533, -104.61203, 1402.0m, 38°  
07/16/2019 03:25:27 PM

### Photo #4

Sinjin E 36-9, 11, 12, 13, 25, LDS F 1-29 Battery

Shut-down