

Inspection Photos
Location Name: A.D Jeffers A#1
Location ID: 323176



Photo 1 loc pic



Photo 2 Rig working on well.

Inspection Photos
Location Name: A.D Jeffers A#1
Location ID: 323176



Photo 3 Stained soil in and around PU motor



Photo 4 Stained soil on PU base from what appears to be from gear box

Inspection Photos
Location Name: A.D Jeffers A#1
Location ID: 323176



Photo 5 Mechanical issue: gear box appears to be leaking



Photo 6 Stained soil around WH

Inspection Photos
Location Name: A.D Jeffers A#1
Location ID: 323176



Photo 7 Stained soil in and around PU base



Photo 8 sep/meter run and ECD

Inspection Photos
Location Name: A.D Jeffers A#1
Location ID: 323176



Photo 9 Stained soil from what appears to be from trucks unloading.



Photo 10 TNK BTRY

Inspection Photos
Location Name: A.D Jeffers A#1
Location ID: 323176



Colorado Oil and Gas Conservation Commission
40.11105, -104.88485, 1508.2m
Jul 16, 2019 12:18:51

Photo 11 TNK BTRY sign faded not legible.