

Inspection Photos
Location Name: Champlin 86 Amoco F #2
Location ID: 319003



Photo 1 New well head sign has been installed.



Photo 2 Weeds have been removed from around PU base