

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
06/27/2019
Submitted Date:
07/17/2019
Document Number:
692401149

FIELD INSPECTION FORM

Loc ID 451937 Inspector Name: Colby, Lou On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
5 Number of Comments
3 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 10598
 Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC
 Address: 123 ROBERT S KERR AVE
 City: OKLAHOMA CITY State: OK Zip: 73102

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		sandridgeenvironmental@sandridgeenergy.com	
Church, Matt	405-651-6853	mchurch@sandridgeenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451937	LOCATION	AC	08/30/2017		-	Shiras CTB S11	RI

General Comment:

This Inspection maybe referred to enforcement; it is being entered for notification and documentation only (CA Dates have not been entered or back dated as appropriate) and is not intended to provide the Operator the opportunity to resolve the alleged violations without the imposition of a penalty, pursuant to Rule 522.c.(1). Operator is directed to perform corrective actions outlined on this inspection report immediately.

This is an Interim Reclamation & Stormwater focused Inspection, a Joint Inspection with Field Inspector Emily Waldron, Any Corrective Actions from previous Inspections that have not been addressed are still applicable. Location was constructed in Fall of 2017. This site lies within a Sensitive Wildlife Habitat; Greater Sage Grouse and CPW Black Bear Area.. Site is 1.6 Miles from Greater Sage Grouse Lek and subject to Wildlife Timing Stipulations. Freshwater Emergent Wetlands are within 100 Ft.

Inspected Facilities

Facility ID: 451937 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? **Fail** _____

Comment **Senesced/dead Russian thistle (now debris) has blown & collected in corners of site. Unknown weed covered waste Material pile at Northeast corner of site.**

Corrective Action **Remove Waste & Debris from site.**

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? Fail Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? Fail
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Fail
 Production areas have been stabilized? Fail Segregated soils have been replaced? Fail

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Fail Recontoured Fail 80% Revegetation Fail

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment Areas no longer needed for Use, Production have not been reclaimed for Interim Reclamation. Location remains at disturbed area of 8 acres. Site should have had Interim Reclamation installed by 11/1/18. Location has no Delayed Interim Reclamation Request In Process or Approved. Operator should consider that unused areas of completed portion of site as well as future expansion area should be included in Interim Reclamation plans.

Corrective Action Reclaim Location for Interim Reclamation per COGCC 1003 Series Rules; installing Reclamation in areas no longer needed for Use, Production. Use appropriate BMPs to stabilize areas until vegetation establishes. Reclamation Activities should have been completed by 11/1/18.

Operator is directed to perform corrective actions outlined on this inspection report immediately

Date 11/01/2018

Overall Interim Reclamation Fail

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____
 Debris removed _____ No disturbance /Location never built _____
 Access Roads Regraded _____ Contoured _____ Culverts removed _____
 Gravel removed _____
 Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____
 Compaction alleviation _____ Dust and erosion control _____
 Non cropland: Revegetated 80% _____ Cropland: perennial forage _____
 Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation

Well Release on Active Location

Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There are serious Stormwater concerns in the area designated as "Future Expansion" on Location drawings. This area was developed during initial construction; but not finished (compacted/graveled/groomed). Sheet flow is occurring across West end, collecting (erosion at intake area) in over full sediment reservoirs (no discharge BMPs evident) washing out berm, eroding and moving sediment off site.

Corrective Action: Install or repair sufficient/effective BMPs in accordance with, and monitoring per Good Engineering Practices per Rule 1002.f.

Operator is directed to perform corrective actions outlined on this inspection report immediately. Performing the CA does not bring Operator into compliance with the rules.

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
692401179	Inspection Photos RI	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4881158