

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/17/2019

Submitted Date:

07/17/2019

Document Number:

687905208

**FIELD INSPECTION FORM**

Loc ID 307017 Inspector Name: Stewart, Joseph On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Findings:**

- 17 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	<a href="#">SW Inspection Reports</a>
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296170	WELL	PR	12/19/2016	GW	067-09562	SOUTHERN UTE 33-10; 21-1 2	PR

**General Comment:**

[Site inspection with photos at the end of this report.](#)

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Labels and placards posted on sign at tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Sign posted at entrance to location.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Contact information posted on sign.		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Cattle panels around wellhead and pumpjack.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Cattle panels around produced water tank.		
Corrective Action:		Date:	
<b>Equipment:</b>			
Type: Submersible Pump	# 1		corrective date
Comment:	In produced water tank.		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:		Date:	

Type: Flow Line	# 8		
Comment:	1-4" flowline from wellhead to separator. 1-2" flowline from separator blowdown to produced water tank. 1-2" flowline from separator dump valve to produced water tank. 1-1" flowline from separator to compressor engine fuel gas. 1-2" flowline from produced water tank electric driven pump to offsite gathering system. 1-2" flowline from separator to compressor suction. 1-2" flowline from compressor discharge to separator outlet. 1-4" flowline from separator outlet to offsite dogleg.		
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:	On produced water tank vent.		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric driven VFD motor on pumpjack with MCC.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	No secondary containment. Double wall tank with level control equipment.			
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 296170 Type: WELL API Number: 067-09562 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Compaction	Pass	Ditches	Pass			
Gradient Terraces	Pass					
				Material Handling And Spill Prevention	Pass	Spill prevention for chemical injection tank.
Berms	Pass	Compaction	Pass			
Ditches	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905218	Location and equipment.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4882157">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4882157</a>
687905219	Location and equipment.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4882158">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4882158</a>