

Inspection Photos  
Location Name: EDKAM #2-23  
Location ID: 332669



Photo 1 WH and WH sign



Photo 2 Sep/meter house and ECD



**Inspection Photos**  
**Location Name: EDKAM #2-23**  
**Location ID: 332669**



**Photo 3 TNK BTRY located in floodplain does not have steel containment.**



**Photo 4 TNK BTRY in floodplain and does not have proper anchoring.**



**Inspection Photos**  
**Location Name: EDKAM #2-23**  
**Location ID: 332669**



**Photo 5 Produced water tank Anchoring installed.**



**Photo 6 HOZ Sep anchoring installed**