

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/16/2019

Submitted Date:

07/18/2019

Document Number:

690900063**FIELD INSPECTION FORM**Loc ID 458558 Inspector Name: FISCHER, ALEX On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10598Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLCAddress: 123 ROBERT S KERR AVECity: OKLAHOMA CITY State: OK Zip: 73102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Colby, Lou		lou.colby@state.co.us	
Laird, Spence		sandridgeenvironmental@sandridgeenergy.com	
Inspections, General		sandridgeenvironmental@sandridgeenergy.com	All Inspections
Neidel, Kris		kris.neidel@state.co.us	
Waldron, Emily		emily.waldron@state.co.us	
Church, Matt		mchurch@sandridgeenergy.com	

General Comment:

On July 16, 2019, COGCC Environmental Staff (Alex Fischer and Kris Neidel) conducted a field inspection of SandRidge Exploration & Production LLC's (SandRidge) Marmot 0880 S19 CTB Location (Location ID: 458558). Matt Church with SandRidge was also on Location. Weather was sunny and temperatures were high 70s degrees Fahrenheit and a steady wind from the south.

The following is a summary:

- Heavy equipment (scraper, excavator, tractor and dozer) on site.
- 4X Industrial on site to install silt fence around location perimeter.
- Three (3) spools of approximate 4-inch pipeline located near the southern portion of the location.
- Approximately 10+/- acres of sage brush and vegetation recently grubbed.
- Three (3) well stake locations were observed.
- Soil is very sandy and unstable even within the non-grubbed area.
- No Location signs present.

COGCC Comments

Comment	User	Date
<ul style="list-style-type: none"> • Heavy equipment (scraper, excavator, tractor and dozer) on site. • 4X Industrial on site to install silt fence around location perimeter. • Three (3) spools of approximate 4-inch pipeline located near the southern portion of the location. • Approximately 10+/- acres of sage brush and vegetation recently grubbed. • Three (3) well stake locations were observed. • Soil is very sandy and unstable even within the non-grubbed area. • No Location signs present. <p>COGCC File Review:</p> <ul style="list-style-type: none"> • Form 2A (Document Number 40144287) approved on 10/31/18. • Form 2A approved for one (1) well, 12 oil tanks, and 7 produced water tanks. • Form 2A approved for incoming off-site pipeline, 8-inches or smaller, schedule 40 steel. • Form 2A, groundwater estimated to be 40 feet below ground surface. 	fischera	07/18/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690900064	INSP Photo Marmot Location 458558 20180716	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4882798