

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/18/2019

Submitted Date:

07/18/2019

Document Number:

696500166

**FIELD INSPECTION FORM**

Loc ID 424006 Inspector Name: Peterson, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**  
 OGCC Operator Number: 10110  
 Name of Operator: GREAT WESTERN OPERATING COMPANY LLC  
 Address: 1001 17TH STREET #2000  
 City: DENVER State: CO Zip: 80202

**Findings:**  
9 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                       | Comment |
|--------------|-------|-----------------------------|---------|
|              |       | cogccinspections@gwogco.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 424004      | WELL | SI     | 07/01/2018  | OW         | 123-33831 | Margil 34A    | SI          |
| 424009      | WELL | SI     | 06/01/2018  | GW         | 123-33834 | Margil 34KD   | SI          |
| 424010      | WELL | SI     | 07/01/2018  | GW         | 123-33835 | Margil 21-34D | SI          |
| 424014      | WELL | SI     | 05/01/2018  | OW         | 123-33838 | Margil 11-34D | SI          |
| 424022      | WELL | SI     | 04/01/2018  | OW         | 123-33841 | Margil 12-34D | SI          |
| 424023      | WELL | SI     | 07/01/2018  | GW         | 123-33842 | Margil 22-34D | SI          |

**General Comment:**  
[FIRR document #402028687](#)

| <b>Location</b>  |  |        |                 |
|--|--|--------|-----------------|
| <b>Lease Road:</b>                                     |  |        |                 |
| Type   | Access   |        |                 |
| comment:   | Access road maintenance noted in prior inspection document #674301654 has been corrected. See attached photos.               |        |                 |
| Corrective ActionL                                     |  | Date:  |                 |
| Overall Good: <input type="checkbox"/>                 |  |        |                 |
| <b>Signs/Marker:</b>                                   |  |        |                 |
| Type   | BATTERY  |        |                 |
| Comment:   |  |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| Type   | TANK LABELS/PLACARDS   |        |                 |
| Comment:   | Produced water vault capacity placard noted in prior inspection document #674301654 has been corrected. See attached photos. |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| Type   | OTHER  |        |                 |
| Comment:   | Lease road entrance  |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| Type   | WELLHEAD   |        |                 |
| Comment:   | x 6  |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| Emergency Contact Number:                              |  |        |                 |
| Comment:   | <input style="width: 100%;" type="text"/>  |        |                 |
| Corrective Action:                                     | <input style="width: 100%;" type="text"/>  |        | Date: _____     |
| <b>Good Housekeeping:</b>                              |  |        |                 |
| Type   | UNUSED EQUIPMENT   |        |                 |
| Comment:   | Unused equipment noted in prior inspection document #674301654 has been removed. See attached photos.                        |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| Overall Good: <input type="checkbox"/>                 |  |        |                 |
| <b>Spills:</b>   |  |        |                 |
| Type   | Area   | Volume |                 |
| In Containment: No                                     |  |        |                 |
| Comment:   | <input style="width: 100%;" type="text"/>  |        |                 |
| <input type="checkbox"/> Multiple Spills and Releases? |  |        |                 |
| <b>Fencing/:</b>                                       |  |        |                 |
| Type   | LOCATION   |        |                 |
| Comment:   | Silt fencing   |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| <b>Equipment:</b>                                      |  |        |                 |
| Type: Compressor                                       | # 1  |        | corrective date |

|                                   |   |  |       |
|-----------------------------------|---|--|-------|
| Comment:                          |   |  |       |
| Corrective Action:                |   |  | Date: |
| Type: Horizontal Heated Separator | # 6                                       |  |       |
| Comment:                          |   |  |       |
| Corrective Action:                |   |  | Date: |
| Type: Plunger Lift                | # 6                                       |  |       |
| Comment:                          |   |  |       |
| Corrective Action:                |   |  | Date: |
| Type: Emission Control Device     | # 2                                       |  |       |
| Comment:                          |   |  |       |
| Corrective Action:                |   |  | Date: |
| Type: Bradenhead                  | # 6                                       |  |       |
| Comment:                          | Bradenhead valves are exposed at surface. |  |       |
| Corrective Action:                |   |  | Date: |
| Type: Pig Station                 | # 1                                       |  |       |
| Comment:                          |   |  |       |
| Corrective Action:                |   |  | Date: |
| Type: Bird Protectors             | # 8                                       |  |       |
| Comment:                          |   |  |       |
| Corrective Action:                |   |  | Date: |
| Type: Gas Meter Run               | # 1                                       |  |       |
| Comment:                          | Multiple tube meter run                   |  |       |
| Corrective Action:                |   |  | Date: |

**Tanks and Berms:**

| Contents           | # | Capacity | Type           | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER     | 2 | 200 BBLs | PBV FIBERGLASS |         |        |
| Comment:           |   |          |                |         |        |
| Corrective Action: |   |          |                |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents  | # | Capacity | Type      | Tank ID | SE GPS                |
|-----------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 6 | 300 BBLs | STEEL AST |         | 40.273220,-104.994430 |

|                    |  |       |
|--------------------|--|-------|
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 424004 Type: WELL API Number: 123-33831 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

Facility ID: 424009 Type: WELL API Number: 123-33834 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

Facility ID: 424010 Type: WELL API Number: 123-33835 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

Facility ID: 424014 Type: WELL API Number: 123-33838 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

Facility ID: 424022 Type: WELL API Number: 123-33841 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

Facility ID: 424023 Type: WELL API Number: 123-33842 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description         | URL   |
|--------------|---------------------|---|
| 696500166    | INSPECTION APPROVED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4883832">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4883832</a> |
| 696500167    | Photos              | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4883789">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4883789</a> |