

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/11/2019

Submitted Date:

07/12/2019

Document Number:

696300329**FIELD INSPECTION FORM**

Loc ID 418854 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
Barber, Matt		mbarber@hpres.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418848	WELL	SI	02/01/2019	OW	123-32032	Lion Creek 03-14H	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	North Loadline bucket is missing the lid, potential wildlife hazard, see photo #5		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	08/19/2019
Type	OTHER		
Comment:	North Loadline bucket appears to have a small leak, buck is full and leaked onto the ground.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	08/12/2019
Type	OTHER		
Comment:	Stained Soil at wellhead, see photo #4		
Corrective Action:	For localized spotting of oily waste - "Properly treat or dispose of oily waste in accordance with 907.e."	Date:	08/12/2019
Type	OTHER		
Comment:	Stained soil at north Loadline bucket, see photo #5		
Corrective Action:	For localized spotting of oily waste - "Properly treat or dispose of oily waste in accordance with 907.e."	Date:	08/12/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			
Type: Pump Jack	# 1		corrective date
Comment:			

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electrical Panels and POC Panel		
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Flare	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	

Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:				Shares berm with Crude Oil Tanks		
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	3	400 BBLs	STEEL AST		40.914550,-104.504670	
Comment:						
Corrective Action:				Date:		
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:				Date:		
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:				Date:		
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:				Date:		

Inspected FacilitiesFacility ID: 418848 Type: WELL API Number: 123-32032 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: TA

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 07/11/2019 at approximately 14:55 PM, I, Inspector Erica Petrie, conducted a Field Inspection at Highpoint Operating Corp., Lion Creek 3-14H, at Location # 418854 in Weld County, Colorado.</p> <p>While there, I observed Production</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Stained soil at Wellhead, see photo #4, Comply with Rule 907.e, CA Date of 08.12.2019</p> <p>Stained soil at Loadline Bucket, see photo #5, Comply with Rule 907.e, CA Date of 08.12.2019</p> <p>Appear to be a small leak at the Loadline Bucket, see photo #5, Comply with Rule 605.d, CA date of 08.12.2019</p> <p>Loadline Bucket missing lid, potential wildlife hazard, see photo #5, Comply with Rule 605.d, CA date 08.12.2019</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	petrie	07/12/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402107539	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4877620
696300330	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4877611