

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
07/19/2019
Submitted Date:
07/19/2019
Document Number:
687905258

FIELD INSPECTION FORM

Loc ID 320857 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
20 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 10000
 Name of Operator: BP AMERICA PRODUCTION COMPANY
 Address: 1199 MAIN AVENUE SUITE 101
 City: DURANGO State: CO Zip: 81301

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Inspections, All		SanJuanCOGCC@bp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205245	WELL	PR	02/01/2001	GW	007-06123	SEIBEL A 1	PR
442577	WELL	PR	01/05/2016	LO	007-06317	Seibel A 2	PR

General Comment:
[Site inspection with photos at the end of this report.](#)

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Labels/placards posted on tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Signs posted at entrance to location.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Emergency contact information posted on signs.		Date: _____
Corrective Action:			
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Wellhead valve sitting on ground by pumpjack.		
Corrective Action:	Remove unused equipment per Rule 603.f.		Date: 08/29/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Cattle panels around wellheads and pumpjacks/LRP's.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Cattle panels around separators, meter houses and piping tie-in points.		
Corrective Action:		Date:	
Equipment:			
Type: Gas Meter Run	# 2		corrective date
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 7		
Comment:	Wellhead#2: 1-4" flowline from wellhead to separator. 1-2" flowline from wellhead to separator. 1-2" flowline from separator dump valve to produced water tank. 1-4" flowline from separator to valve cluster tie-in point @6" rack. 1-2" flowline from produced water tank to electric transfer pump. 1-2" flowline from electric transfer pump to offsite produced water gathering system. 1-2" flowline from offsite gathering system to produced water tank.		
Corrective Action:		Date:	
Type: Flow Line	# 1		

Comment:	*1-1" domestic gas tap from separator to offsite natural gas powered engine for center pivot irrigation system. Currently open and in use.			Date:	
Corrective Action:				Date:	
Type: Ancillary equipment	# 2				
Comment:	Wellheads.			Date:	
Corrective Action:				Date:	
Type: Bradenhead	# 2				
Comment:	PVC bradenhead access.			Date:	
Corrective Action:				Date:	
Type: Flow Line	# 5				
Comment:	Wellhead #1: 1-3" flowline from wellhead to separator. 1-2" flowline from separator dump valve to produced water tank. 1-2" flowline from separator to meter house. 1-2" flowline from meter house to valve cluster tie-in point @6" rack to offsite. 1-1" flowline from separator to heated tank fuel gas.			Date:	
Corrective Action:				Date:	
Type: Bird Protectors	# 3				
Comment:	(1) on heated tank, (2) on separator stacks.			Date:	
Corrective Action:				Date:	
Type: Vertical Heated Separator	# 2				
Comment:				Date:	
Corrective Action:				Date:	
Type: Prime Mover	# 2				
Comment:	Electric VFD driven motors on pumpjack/LRP with MCC's.			Date:	
Corrective Action:				Date:	
Type: Pump Jack	# 2				
Comment:	Pumpjack and Linear rod pump.			Date:	
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	HEATED STEEL AST		,
Comment:	Produced water tank has electric transfer pump to move produced water offsite.				Date:
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 205245 Type: WELL API Number: 007-06123 Status: PR Insp. Status: PR

Producing Well

Comment: Producing.

Corrective Action:

Date:

Facility ID: 442577 Type: WELL API Number: 007-06317 Status: PR Insp. Status: PR

Producing Well

Comment: Producing.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Culverts	Pass			
Ditches	Pass	Ditches	Pass			
Berms	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905268	Unused equipment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4885035
687905269	Location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4885036
687905270	Location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4885037
687905271	Domestic gas tap.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4885038