

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/15/2019

Submitted Date:

07/21/2019

Document Number:

698600087**FIELD INSPECTION FORM**Loc ID 402779 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 83700Name of Operator: SUMMIT OIL COAddress: 5299 DTC BLVDCity: ENGLEWOOD State: CO Zip: 80111-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236227	WELL	DA	07/21/1972	DA	121-08717	VONDY 3	DA

General Comment:

This is an orphaned well inspection. Inspection completed to document progress and completion of plug and abandonment task..

Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program.

See link at end of report for path to downloadable pictures.

Location

Lease Road:			
Type	Access		
comment:	No access road. Well is located in plowed field. After meeting with landowner access will from field access in SW corner and N along edge of field and then E into well site.		
Corrective Action	L	Date:	

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date: _____
Corrective Action:		

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Casing and casing cap cleaned up and working wellhead welded onto casing.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 236227 Type: WELL API Number: 121-08717 Status: DA Insp. Status: DA**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Dry and abandoned well drilled in 1972. Well was brought to COGCC attention through complaint with water showing at PA location. Environmental inspection of Complaint #200440829 - water surfacing at PA well location was conducted 12/30/2017. Well was placed on Orphaned Well List and is the process of being plugged.

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>The Vondy 3 Plugging Project is underway. The Vondy 3 site consist of dry and abandoned well that has started leaking water to the surface. Well was brought to COGCC attention through complaint filed by landowner that water was surfacing at PA location. Environmental inspection of Complaint #200440829 - water surfacing at PA well location was conducted 12/30/2017. Well was placed on Orphaned Well List and is the process of being plugged. This inspection was performed as work was completed installing a working wellhead on surface casing for entry and plugging work.</p> <p>Met Excell Services at site. Surface casing cap was cut and wellhead with 4' drop pipe was set into surface casing. Wellhead was welded into place and well was shut in. Additional pin leaks were identified in casing cap weld and pipe surface. Welder repaired leaks and area was backfilled and prepped for placement of balance beam.</p> <p>Work site was secured.</p>	stjohnw	07/20/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600088	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4885328